

Fire Appliance Summary

Client: ESSENTIAL SAFETY TEST
Site: ESS Burwood. Location: All.
11/01/16 - 19/12/16



Service Name	Appliances Passed	Appliances Failed	Total Tested
Fire Blanket Service	1	0	1
L1 Fire Extinguisher	2	0	2
L1 Month Fire Hose Reel	1	0	1
L2 Fire Hose Reel	1	0	1
	5	0	5



Client: ESSENTIAL SAFETY TEST

Site: ESS Burwood

Location: L1 CORRIDOR

Asset ID	Appliance Type & Size	Make & Rating	DOM & NPT Dates	Date	Next Test	Result
GN300039120	9kg Dry Powder Ext	FLAMESTOP 6A80BE	12/2012 12/2017	12/12/16	12/06/17	Pass
GN300039121	4.5kg Dry Powder Ext	CHUBB 4A60BE	12/2012 12/2017	12/12/16	12/06/17	Pass
GN300039122	1.2 x 1.2 FIRE BLANKET	FIREGARD	N/A	12/12/16	12/06/17	Pass
GN300039123	36M 19mm Hose Reel	LKS	12/2014	12/12/16	12/06/17	Pass
GN300039124	36M 19mm Hose Reel	LKS	12/2014	12/12/16	12/06/17	Pass

Total Tests: 5



PHIL HOPPE
CERT II Fire - XXX
FPAS - xxxxxx

Client: ESSENTIAL SAFETY TEST

Site: ESS Burwood

Location: L1 CORRIDOR

Asset ID: GN300039120	Appliance Type & Size: 9kg Dry Powder Ext	Make & Rating: FLAMESTOP 6A80BE	DOM & NPT Dates: 12/2012 12/2017	Service Lev
-----------------------	---	---------------------------------	----------------------------------	-------------

Comments: SL1

Test Type	Date	Result	Unit	Status
Accessibility	12/12/16			Pass
Anti tamper device	12/12/16			Pass
Exterior & Instruct	12/12/16			Pass
Service Tag	12/12/16			Pass
External Damage	12/12/16			Pass
External Corrosion	12/12/16			Pass
Outlet Hose Assembly	12/12/16			Pass
Pressure Indicator	12/12/16			Pass
Contents Full Charge	12/12/16			Pass
Signage	12/12/16			Pass
Support Bracket	12/12/16			Pass
Discharge nozzle	12/12/16			Pass
Press. Test Current	12/12/16			Pass
Weight	12/12/16	12.3	kg	Pass
Actions	12/12/16	tamper clean tag		Pass

Overall: Pass

Asset ID: GN300039121	Appliance Type & Size: 4.5kg Dry Powder Ext	Make & Rating: CHUBB 4A60BE	DOM & NPT Dates: 12/2012 12/2017	Service Lev
-----------------------	---	-----------------------------	----------------------------------	-------------

Comments: SL1

Test Type	Date	Result	Unit	Status
Accessibility	12/12/16			Pass
Anti tamper device	12/12/16			Pass
Exterior & Instruct	12/12/16			Pass
Service Tag	12/12/16			Pass
External Damage	12/12/16			Pass
External Corrosion	12/12/16			Pass
Outlet Hose Assembly	12/12/16			Pass
Pressure Indicator	12/12/16			Pass
Contents Full Charge	12/12/16			Pass
Signage	12/12/16			Pass
Support Bracket	12/12/16			Pass
Discharge nozzle	12/12/16			Pass
Press. Test Current	12/12/16			Pass
Weight	12/12/16	6.6	kg	Pass
Actions	12/12/16	CLEANED		Pass

Overall: Pass

Asset ID: GN300039122	Appliance Type & Size: 1.2 x 1.2 FIRE BLANKET	Make & Rating: FIREGARD	DOM & NPT Dates: N/A	Service Lev
-----------------------	---	-------------------------	----------------------	-------------

Comments: SL1



Test Type	Date	Result	Unit	Status
Accessibility	12/12/16			Pass
Signage	12/12/16			Pass
Blanket Container	12/12/16			Pass
Fire Blanket	12/12/16			Pass
Marked AS3504 Comply	12/12/16			Pass
Actions	12/12/16	CLEANED		Pass
Overall: Pass				

Asset ID: GN300039123	Appliance Type & Size:36M 19mm Hose Reel	Make & Rating: LKS	DOM & NPT Dates:12/2014	Service Lev
Comments: SL1				
Test Type	Date	Result	Unit	Status
Accessibility	12/12/16			Pass
Signage	12/12/16			Pass
Operating Instruct	12/12/16			Pass
Damage	12/12/16			Pass
Cabinet	12/12/16			Pass
Nozzle Interlock	12/12/16			Pass
Swing Arm	12/12/16			Pass
Leakage	12/12/16			Pass
Service Tag	12/12/16			Pass
Water present	12/12/16	CHECKED WATER CLEANED	yes/no	Pass
Actions	12/12/16	CHECKED WATER CLEANED		Pass
Overall: Pass				

Asset ID: GN300039124	Appliance Type & Size:36M 19mm Hose Reel	Make & Rating: LKS	DOM & NPT Dates:12/2014	Service Lev
Comments: SL1				
Test Type	Date	Result	Unit	Status
Accessibility	12/12/16			Pass
Signage	12/12/16			Pass
Operating Instruct	12/12/16			Pass
Damage	12/12/16			Pass
Cabinet	12/12/16			Pass
Nozzle Interlock	12/12/16			Pass
Swing Arm	12/12/16			Pass
Leakage	12/12/16			Pass
Service Tag	12/12/16			Pass
Anchor Points	12/12/16			Pass
Hose Guide	12/12/16			Pass
Hose Fittings	12/12/16			Pass
Bearings	12/12/16			Pass
HOSE	12/12/16			Pass
Ancillary Equipment	12/12/16			Pass
Fire Hazard	12/12/16			Pass
Overall: Pass				



Obstructions	12/12/16			Pass
Flow Rate	12/12/16	0.42	Ltr/s	Pass
Actions	12/12/16	CHECKED WATER CLEANED		Pass
				Overall: Pass

Total Tests: 5